



CIVIL QUALITY CONSULTANTS & ENGINEERS

(Buildings Geo-Tech & Highway Materials Testing Laboratory)
An ISO 9001: 2008 Certified Company



**ame of Work: Improvements and Re-Asphalting of Road from NH4 to
elamaheshwari Temple Road 2nd & 3rd main Kempegowda Nagara in Dasarahalli Ward
o.15, BBMP, Bangalore.**

ame of Client

: Executive Engineer, Dasarahalli
Division, BBMP, Bangalore.

ontractor/Agency

: Sri. K.T Ramesh, Contractor,
Bangalore.

otal Cost

: Rs. 22.21 Lakhs

atus of Bill

: 1st & Final Bill

ate of Inspection

: 22.03.2018


the Presence of

: (a) Assistant Engineer (Ward No.15),
BBMP, Bangalore.

: (b) Mr. Mohan G. Senior Engineer
M/s Civil Quality Consultants And
Engineers,

3rd Partuy Compliance Report

L o	Description of the Item	Unit	Quantity	Comments / observations
	Removing BS slab of drain and stacking complete as per the direction of Engineer-in-charge.....	Sqm	1112.76	: Work done up to the billed quantity and Quality is satisfactory
2	Earthwork excavation by manual means in ordinary soil involving an average horizontal throw upto 2mtrs.....	Cum	401.83	: Work done up to the billed quantity and Quality is satisfactory
3	Refixing stone slabs of drains and pointing in CM 1:3.....	Sqm	1112.76	: Work done up to the billed quantity and Quality is satisfactory
4	Compaction of original ground with maximum of 6 passes of 8 to 10 tonnes.....	Sqm	663.20	: Work done up to the billed quantity and Quality is satisfactory
5	For grading I material Construction of granular Sub-base by Providing coarse graded crushed stone aggregates.....	Cum	99.48	: Work done up to the billed quantity and Quality is satisfactory
5	Providing, laying, spreading and compacting stone aggregate to wet mix macadam.....	Cum	99.48	: Work done up to the billed quantity and Quality is satisfactory



Office & Laboratory : # 133, Bhuvaneshwari Nagar, Dodda Basti Main Road, Bangalore - 560 056
e-mail: civilqualityconsultants@gmail.com Ph: 080-23240644 / Mob: 8553518550



CIVIL QUALITY CONSULTANTS & ENGINEERS

(Buildings Geo-Tech & Highway Materials Testing Laboratory)

An ISO 9001: 2008 Certified Company



Providing and applying primer coat with S.S bitumen on prepared surface of granular base.....	Sqm	663.20	: Work done up to the billed quantity and Quality is satisfactory
Providing and applying tack coat on the prepared black topped surface	Sqm	8243.80	: Work done up to the billed quantity and Quality is satisfactory
Providing and laying bituminous macadam on prepared surface with crushed coarse aggregates.....	Cum	33.16	: Work done up to the billed quantity and Quality is satisfactory
Cleaning the existing black topped surface with brooms, soft brushes and finally dusting with old gunny bags.....	Sqm	7580.64	: Work done up to the billed quantity and Quality is satisfactory
Providing and laying bituminous concrete with hot mix plant using crushed aggregates of specified grading.....	Cum	225.12	: Work done up to the billed quantity and Quality is satisfactory
Road marking with Hot applied Thermoplastic Compound with Reflectrising Glass Beads.....	Sqm	190.74	: Work done up to the billed quantity and Quality is satisfactory



Authorised Signatory
For CIVIL QUALITY CONSULTANTS & ENGINEERS

Authorised Signatory

[Handwritten signature]

[Handwritten signature]
ಕಾರ್ಯದರ್ಶಿ
ಬಿ.ದಾಸರಾಜ್, ಉಪ-ವಿಭಾಗ
ವಾಗಲೂರು, ಬಿಬಿಎಂಪಿ
ಬೆಂಗಳೂರು